


Earthquake repairs to Elmdale Lane - Unit 7

Extent of work:

- Gap filling - 40 metres
- Gib stopping - 2 m²
- Repainting of internal walls & ceilings - 111 m²
- Fill gaps to architraves and repaint - 5 m
- Install plates to concrete tilt panel join to avoid further separation
- Replace timber roof support to underside of roofing - 8m
- Repair damaged ceiling grid
- Prepare concrete floor & replace carpet and underlay to foyer - 28m²
- Prepare concrete floor and replace carpet tiles to warehouse - 8 m²
- Lift and relay carpet to kitchen area for floor crack repairs - 15m²
- Epoxy injection concrete wall crack repairs - 6.0 metre
- Epoxy injection concrete floor crack repairs - 12 metres





STAKE CONSULTING LTD

Job Reference: 7 ELMDALE LANE

Start Date: 1/11/2011

Image Issues: 4

Text Issues: 0

EPOXY SST PANEL INJECTION PHOTO

EPOXY SST PANEL INJECTION

PHOTO :

LOCATION: CARPARK


REPAIR CODE SST

FLOOR CRACKING

SCAFFOLD NOT REQUIRED

TOTAL 1.2m

NOTE: SEEN FROM INSIDE.



EPOXY GFI FLOOR INJECTION PHOTO

EPOXY GFI FLOOR INJECTION

PHOTO : 1

LOCATION: FLOOR

REPAIR CODE SST

FLOOR CRACKING

SCAFFOLD NOT REQUIRED

TOTAL 12m

NOTE:



EPOXY SST PANEL INJECTION PHOTO

EPOXY SST PANEL INJECTION

PHOTO : 2

LOCATION: BACK WALL

REPAIR CODE SST

FLOOR CRACKING

SCAFFOLD NOT REQUIRED

TOTAL 2.6m

NOTE:



EPOXY SST PANEL INJECTION PHOTO

EPOXY GFI FLOOR INJECTION

PHOTO : 3

LOCATION: BACK WALL

REPAIR CODE SST

FLOOR CRACKING

SCAFFOLD NOT REQUIRED

TOTAL 2.2m

NOTE:

