


Earthquake repairs to Elmdale Lane - Unit 5

Extent of work:

- Gap filling - 4 metres
- Gib stopping - 15 m2
- Repainting of internal walls/ceilings - 81 m2
- Replace framing, lining and scotia to collapsed store room & wash room ceiling - 14 m2
- Repainting to external tilt panel walls - 11 m2
- Epoxy injection concrete wall crack repairs - 4.0 metres
- Epoxy injection concrete floor crack repairs - 24.7 metres





STAKE CONSULTING LTD

Job Reference: ELMDALE LANE UNIT 5

Start Date: 1/11/2011

Image Issues: 2

Text Issues: 0

EPOXY SST PANEL INJECTION

EPOXY SST PANEL INJECTION


PHOTO 1

LOCATION: NORTH WALL PANEL

REPAIR CODE SST

SCAFFOLD REQUIRED

TOTAL METRES 4



EPOXY GFI PANEL INJECTION

EPOXY GFI FLOOR INJECTION

PHOTO 2

LOCATION: WAREHOUSE FLOOR

REPAIR CODE GFI

TOTAL METRES 24.7

