

# SITE REPORT



## FIRE

SR No **F1**  
Job Name **5-7 Elmdale Lane**  
Job No **241596**  
Date **07 October 2025**  
To **Baileys**  
Address **steven.schwalger@bayleyscanterbury.co.nz**  
Attention **Steven Schwalger**  
Copies to  
Issued By **Taufiq Anuar**

P 03 366 1777  
E [engineering@pfc.co.nz](mailto:engineering@pfc.co.nz)  
W [pfc.co.nz](http://pfc.co.nz)

Reason ☒ **Construction Monitoring** ☐ **Client Request** ☐ **Contractor Request**  
☐ **Owner Request** ☐ **Other (Specify):**

Date and time of visit **07 October 2025 08:00AM**

### Health & Safety (select one)

- ☐ Site Hazard Board reviewed and no unidentified issues to be communicated  
☐ Site Hazard Board reviewed and issues identified below  
☒ Site hazards assessed (no Hazard Board)

### 1. Current progress on site

Inspection carried out on 07 October 2025 was for the inspection of the completed construction of lightweight fire separation.

The PS3 from the contractor, Brendan Hammon Building Contractors Ltd, has been provided.

### 2. Items for Action/ Comment

- Please have Brendan amend the PS3 to state "...**GIB** GBT 120**b** System."
- As per the Fire Letter, please have the contractor assess the existing IT concrete wall and seal all visible cracks and gaps with a fire rated sealant. As pointed out, the gap between the concrete wall and the perpendicular external wall will require to be sealed on both sides. Please refer to the photo below:



Please send through email confirmation and photos, once completed.