

Defect Notice

Agent Name: Rene Villanueva
Date: 20-11-2025
Document no: 18420457520



SITE INFORMATION

Branch	JCI Service Wellington
Site ID	58939-01
Site Name	ARROW MAT SERVICES (TENANT)
Street NO/Address	1D QUADRANT DR
Town/City	LOWER HUTT CENTRAL
Day Date / Time	Nov 20, 2025 9:47:00 AM NZDT
The Following Defect/s Were Found During Our:	Monthly Test

DEFECT DESCRIPTIONS

DEFECT	1 OF 2
--------	--------

System	Final Exits (SS15/2)
Defect Description	971169 - repeat
Severity of Defect	Significant
Photos of Defect	




DEFECT

2 OF 2

System
Defect Description
Severity of Defect
Photos of Defect

Fire Separations (SS15/3)
983305 - repeat
Significant



SIGNATURE


Technician Name
Contact Number
Email
Technician Signature

Rene Villanueva
0272406899
rene.villanueva@jci.com

Date

Nov 20, 2025

Additional Document





DISCLOSURE STATEMENT

1. The following information has been supplied to Capital Commercial (2013) Limited ("Bayleys") to be made available for distribution on the vendor's behalf to potential purchasers to assist purchasers with their due diligence and to use at the purchaser's discretion.
2. Bayleys and the Vendor do not warrant the accuracy or completeness of the information and recommends that all recipients undertake their own due diligence, obtain their own reports to their satisfaction and seek independent advice prior to committing to purchaser.