

HANSEN

CONTRACTORS

32 Newnham St
PO Box 32
Rangiora 7440

PH (03) 313 8418
A/H 0274 545 775
www.hansencontractors.co.nz

SERVICE REPORT

Client name: Ashley Hotel Council: WDC

Site address: Ashley

Phone: _____ (home) _____ (work) _____ (mobile)

Serviced by: Joel Clegg Type of system Commercial

CHECK LIST	DONE	COMMENTS	INFORMED OWNER
1. Measure the depth of solids and scum	✓	getting quite thick	
2. Check filters and clean if necessary	✓	due for pumping next service.	
3. Check pump and float switch and alarm	✓		
4. Flush the lines until clear	✓		
5. Pressure testing at end of pipe(s)	✓	-	
6. PH test	✓	-	
7. Control panel complete check	✓		
8. Self cleaning pump filter – remove and clean - refit	✓		
9. Lids and control box	✓		
10. Blower	✓		
11. Aeration	✓		
12. Media	✓		
13. Check the vegetative cover of the effluent discharge	✓		
14. Before leaving: All lids secured, power on, valves and piping in working order	✓		

Signed: [Signature] Date: 12-9-18
(Service Contractor)

Comments: cleaned and serviced - solids chamber getting quite full
(grease trap ok)