





						ENVIRONMENTAL MANAGEM
	FINAL INSPI	= 0	T	10	N SHEET	
	THE THE					2 7 MAR 2015 Far North District Council
Date	12/03/15				Action 305	MAK 2015 Far North District Council
BC#	20,5 270				Time of inspection	AM/PM
	2015-270				Inspection Inspection Description	
Applicant	11 1.6.1				Inspection Wash	200
/Builder	Wadsworth				Description OV FS1	107
					OV to annual risk CCC and institut	Yes No
Property Address	5 Waranga PL Omapere				OK to proceed with CCC application Is a reinspection required	Yes No
Address	Dun 200				Is paperwork required	Yes/No
	Omapere					
Travell	ing Time .					
(from	previous job/office)	Off	icer		Malcolm	
Inspect	ion Time :				MO Do	
		Name and Address of the Owner, where the Owner, which the	natu		Was	
FINAL In		ОК	Not	N/A	Comments	
1	Peer Review required (over 4yrs)			V	under Lys	
3	Is the final pack on site Owners Application for CCC / Contractors list		2			
4	Is the building completed as per plans and specs		/		1	
5	Photos Taken	V			(1) torus	6 last on site los
6	Have conditions on BC been met (Form 5)	~				1 11
7	Have amended plans been approved			/	Owner	to tilling
8	Have all inspections been completed	/				
FINAL Fit	replaces Inspection	ок	Not	N/A	Comments	
1	Smoke Alarms with Hush			T		
2	Hearth size & secured			1		
3	Fire Place clearances Fire Place secured (seismic restraint)					
5	Flue Shield					
	Flashings / Flue height					
7 8	Wet back circulators correct size & fall Wet back system open vented only					
PLUMBIN		ок	Not	N/A	Comments	
1	Washing machine separate waste			1		
2	Gas water heaters - (Califont) - Is gas certificate required?				,	
3	Hotwater cylinder			1		
4	1 metre minimum of copper outlet of HWC					
5	Seismic Restraint					
7	Hot water tempering value set at 45/55 degrees Hot water drain OK (falls to outside of building)					
	Filter, non return, stop, cold water expansion, pressure			1		
9	reducing & pressure relief valves Notches & holes in joists & bearers (Subfloor)					
10	Waste pipes sizing/ fall/ support/ to gully trap					
11	Soil pipe sizing / fall / support					
13	Adequate support to water pipes Water supply pressure tested - is PS3 required					
14	Water supply Tank / bore / supply Water Filtration system installed					
16	Back flow prevention where required			-		
EINAL In	ternal Inspection	OK	Not	N/A	Comments	
1	Smoke alarms with Hush - 3m sleeping areas	- CA	1401	1	Comments	
2	Sink insert secured correctly					
3	Service rooms Impervious walls Service rooms Impervious floors			-		
5	Producer statement membrane in wet areas					
6	Ceiling Insulation					
8	Safety glass where required Ventilation					
9	Stairs gap / tread / rise/ handrails					
10	Barrier height 900 / 1mtr / 1.1mtr / 100mm gaps					
11	Safety from Falling eg. 100mm balustrade gaps Access for disabled - Commercial only					
13	Facilities for disabled - Commercial only					

FINA		-			
	CTERIOR Inspection	OK	Not		Comments
1	Landscaping Complete			V	
2	Joints in bearers supported	1		1	Sout four to cade
3	Ground clearance to u/side of floor	1	/	4	
4	Subfloor ventilation	1			
5	Subfloor bracing	/			11.
6	U/floor Insulation		2	/	Bracine OK
7	Finished ground level	/			
8	Cladding - joints, corner, scribers window flashing etc	/			
	High Risk Junctions - Deflection, Drainage, Drying,				
9	Durability - Check H20 % around openings				
10	Cladding- painted / penetrations sealed	V			
11	Brick veneer weep holes cleared			/	
12	Roof & post fixings	1		/	
13	Roof, ridging & flashings fixed correctly			/	
14	Roof penetrations flashed correctly			~	
15	Spouting fixed correctly		-		can a card director
		-			Sparting Exigend dips OF
16	Down pipe clips at 1.2				
17	Vent pipe clips at 1.2			-	
18	Vent Discharge/Vermin Cage			/	
19	Stairs gap / tread / rise/ handrails			-	
20	Barriers 1.0m /1.1m /Stairs 900mm			-	
21	Safe from Falling Balustrades			-	
22	RAMPS grade / slip resistance			1	
23	Safety Glass (Glass Visible-commercial)				
	The second second second				
DRAINA	GE .	OK	Not	N/A	Comments
1	Asbuilt drainage plan s/water and sewer				
2	Gully dish 25 mm above sealed surface "A"				
			1000		
3	Gully dish 75mm above unsealed surface "B"				
4	Relief gully installed - (ORG)				
5	Ventilation to drains e.g. TV & or valves				
6	Stormwater drain finished as per approved plan	2			Stormwater out to lead
7	Overflow from water tank to approved outlet				
	Retaining wall drainage connected into stormwater				
8	drain				
9	Effluent disposal installed to TP58		101		
10	Access for septic tank maintenance				
	Commissioning Statements/ Maintenance Contract -				
11	AWTS Systems				
12	Effluent Completed Barking/Planting/Fencing	11.75	970		
		180		-	
Producer	Statements	OK	Not	N/A	Comments
1	Engineer / Licenced Building Practioneer	1			PSI ONLY
2	Plumbing / Drainage pressure tests			1	
3	Membranes - Roof / Decks / Gutters			1	
				V	
FINAL PO	OOL Inspection	OK	Not	N/A	Comments
1	Pool Fencing Compliance. (Sheet completed)		1	_	
2	Back flow prevention where required				
			1	1	
ENERGY	CERTIFICATES	OK	Not	N/A	Comments
1	Electrical	TV		X	to pover ES anto MMal
2	Gas			/	
			1		
ROAD DA			Not	N/A	Comments
1	Footpath & kerb damage	V	/		
2	Crossing installed	V			
		0		N1/6	
COMME		OK	Not	N/A	Comments
1	Check draft Compliance Schedule				
2	Fire Design Compliance				
3	FPIS Report (All Type 2 to 7 systems)				
4	Is a Certificate of Public Use required				
5	Producer Statements for Specified Systems				
6	Accessible Facilities (Carpark, Access, WC etc)				
7	ISO Signage for accessible facilities				
AND DESCRIPTION OF	CTED BUILDING WORK - LBP's Record of Work -		1994		
	Form 5 for requested Records of Work)	OK	NOT	NA	Comments
1	Are all RoW's received	JA			
2	Form 2c - Notice of Owner-Builder				
		1			
3	Does a complaint have to be laid with LBPB	1			
			1		
				X	
				1	
























FAR NORTH DISTRICT COUNCIL

Field Advice Notice - Building 1

Previous Inspection Checked Yes / No

Free Phone: 0800 920 029 Phone: 09 401 5200 Fax: 09 401 0987 www.fndc.govt.nz

Private Bag 752, Memorial Ave, Kaikohe

Applicant: Builder:

Site Address:

VAL# **Travelling Time:** Inspection:

Passed / Failed

Reinspection Required:

Yes / No

Inspection Time:

Officer:	malcolm				Signature: 14151
209 FOU	UNDATION Inspection / 208 Footings	OK	Not 1	N/A	CommentsIf further inspection needed please indicate
1	Boundary pegs sited				
1	Correct site & building siting (Closer than 1.1m to boundary surveyors Certificate required)	6			(209)
2	Ground bearing, fill, expansive clay	6			
3	Reinforcing: Spacing, size, clearance etc			600	
4	Excavation: Depth, width		/	6	1 1 1 1
5	Pile/Pole holes: Depth, diameter	-	/		100 Condition or consect
6	Pile/Pole: Correct grade, diameter	-			
7	Driven Piles: Engineers Certification			4	
8	Retaining Wall: Polythene underneath			Seed.	(Last)
9	Other				100 ar per fron
UND	DER SLAB PLUMBING Inspection	ОК	Not I	N/A	
1	Pipes: gradient, protection, sizing, tested				
2	Other				
NAME OF TAXABLE PARTY OF TAXABLE PARTY.	B Inspection / 214 TILT slab inspection	OK	Not 1	N/A	OV + ONE
1	Slab Thickness: D.P.M., tape, rebates				OF 10 1000
2	Slab Reinforcing: Thickenings, tying cover etc				
3	Fill: Compaction, depth, binding				
4	Other				
217 SUB	FLOOR Inspection	OK	Not I	V/A	
1	Sub floor brace connectors				
2	Bracing: Washers, timber size etc				
3	Bearer/Joist: Size, spacing, joist hangers				
4	Notching/Holes/Blocking for lines of horizontal supports				
5	Ventilation & Insulation				
6	Other				
221 BON	ID BEAM - SUSPENDED SLAB Inspection	OK	Not I	N/A	The second secon
1	Block size				
	Reinforcing: Size, grade, laps, tied				
3	Washouts: If pour exceed 1.2m in height				
4	Design calculation on site				
5	Retaining Wall: DPM, type, protection, Novacoil siting				
6	Adequate propping				
7	Service Installation (Fire Collars)				
8	Identify proprietary pre-stress components				
9	Other		-		
	SHING / 224 CAVITY Inspection / CK VENEER Inspection	ок	Not I	N/A	
1	Flashings				
2	Battening (air cavity)				
3	Wrap				
4	Vermin protection				
5	Bricks / Blocks: Fixings Control joints flashings				
	Rebate clean and clear - Washouts				
7	Brick Ties SS / Galv				
-	Check complex roof details				
NORTH DESIGNATION OF THE PERSONS ASSESSMENT	Other				
230 Firep	place Chimney Inspection	OK	Not 1	N/A	
1	Solid fuel heating, chimney check, setback fixing,		1000		
	flue flashing, mantel shelf, hearth construction				
	Other				
	nming Pool Fence Inspection	OK .	Not 1	V/A	
1	Swimming Pool: backwash, fencing, registration		Be a		

An inspection of the above mentioned premises has been undertaken and the matters as listed above must be completed within.....days or otherwise stated

Action to be taken:

Issued By:

This Notice Received By:

Designation:

Next Inspection: